

**NAVAL FACILITIES ENGINEERING COMMAND  
CONTRACTOR INCIDENT  
FY98 SUMMARY**



**38 STRUCK BY/AGAINST/CAUGHT BETWEEN:**

- 23 involving being struck by object (1 amputation; 5 fractures)
- 8 involving being caught-in/between objects (1 **DEATH**; 2 amputations; 3 fractures)
- 7 involving striking against an object (1 fracture)

**33 FALLS:**

- 10 involving scaffolding (2 fracture)
- 7 involving ladders (2 fractures)
- 6 involving slips/trips same level
- 3 involving stairs/improper openings
- 2 involving roofs (1 **DEATH**; 1 fracture)
- 2 involving improper work platforms
- 2 involving aerial lift platform/man basket (1 **DEATH**)
- 1 involving truck (1 fracture)

**5 ELECTRICAL:**

- 3 involving electrical shock
- 2 involving cutting/striking electrical circuits

**6 MOTOR VEHICAL:**

- 3 involving being struck by (1 **DEATH**)
- 1 involving striking an object
- 2 involving property damage only

**8 EXPOSURE TO/CONTACT WITH:**

- 4 involving exposure to dust/foreign bodies
- 3 involving release of steam/hot water
- 1 involving exposure to heat

**8 LIFTING/EXERTION:**

- 5 involving lifting
- 3 involving exertion

**1 FIRE:**

- 1 involving propane torch

**7 CRANE/RIGGING:**


- 3 involving property damage
- 2 involving struck by situation (2 fracture)
- 1 involving man basket
- 1 involving caught between situations (1 fracture)

**5 OTHER:**


- 3 involving muscle strain from slip/trip/twisting
- 1 involving improper work position
- 1 involving property damage to GOV

\*\*\*\*\*


# CONTRACTOR ACCIDENT TYPES FY96 - FY98 COMPARISON




# CONTRACTOR ACCIDENT TYPES COMPARISON BY PERCENTAGE



FY96 % OF MISHAPS REPORTED



FY97 % OF MISHAPS REPORTED



FY98 % OF MISHAPS REPORTED